

Poly Pickup Bands

For Agco, Case IH, Challenger, Hesston, John Deere, Massey Ferguson, New Holland, New Idea & Vermeer

Increase performance and make used equipment look new again!

These poly bands are made heavy to eliminate the problem of bending and wearing and will withstand impacts without damage. If pickup teeth do rub against the bands, they will not wear through nearly as quickly as with steel bands. In addition, hay feeds through much more smoothly and easily. The ½ inch thick bands have a ¼ inch support ring on the inside to strengthen and maintain shape.

Longer bolts (included) are required to attach the poly bands.



Go from this...



To this!



Flexible · Reduced Tooth Wear · Less Noise · Maintained Colour



Find a local dealer



Poly Pickup Bands

The poly pick up band features a flexible high impact poly. It has a quarter inch support ring on the inside to strengthen and maintain its shape. Longer bolts are required which are included with part.

AGCO



Agco Square Baler

Models: 7433, 7434, 7444, 7423, 7424
Replaces: 700141909, 700189742

Part No.	Description	Suggested List Price
PUPPBBSHS	Agco, Challenger, MF Poly Pickup Band	35.74

CASE IH



Case IH Big Square Baler (with Roto Cutter Head)

Models: LB334, LB434, LB333, LB433, LBX331, LBX332, LBX421, LBX422, LBX431, LBX432
Replaces: 84607781, 84274384

Part No.	Description	Suggested List Price
PUPPBRCNH-B	CIH Poly Pickup Band	44.32

CASE IH



Case IH Square Baler

Models: 8550, 8570, 8575, 8585
Replaces: 700108607, 700129658

Part No.	Description	Suggested List Price
PUPPBTONH-S	CIH, Challenger, Hesston, New Idea Poly Pickup Band	44.32

CHALLENGER



Challenger Square Baler

Models: LB33, LB34, LB44
Replaces: 700108607, 700129658

Part No.	Description	Suggested List Price
PUPPBTONH-S	CIH, Challenger, Hesston, New Idea Poly Pickup Band	44.32

Case IH Big Square Baler with Standard and Packer Cutter Head

Models: LB334, LB434, LB333, LB433, LBX331, LBX332, LBX421, LBX422, LBX431, LBX432 (No balers with rotary cutter)
Replaces: 84468627, 84607815, 84801631, 84214800, 84274387



Part No.	Description	Suggested List Price
PUPPBTONH-B	CIH Poly Pickup Band	35.74

Challenger Square and Round Balers

Models: Square 2150, 2170, 2190, 2250, 2270, 2290
Models: Round RB46, RB56
Replaces: 700141909, 700189742



Part No.	Description	Suggested List Price
PUPPBBSHS	Agco, Challenger, MF Poly Pickup Band	35.74



Poly Pickup Bands (cont'd)

HESSTON

Hesston Square Baler

Models: 4750, 4755, 4760, 4790
Replaces: 700108607, 700129658



Part No.	Description	Suggested List Price
PUPPBTONH-S	CIH, Challenger, Hesston, New Idea Poly Pickup Band	44.32

MASSEY FERGUSON

Massey Ferguson Square & Round Balers

Square Models: 2150, 2170, 2190, 2250, 2270, 2290
Round Models: 2846, 2856, 2946, 2956
Replaces: 700141909, 700189742



Part No.	Description	Suggested List Price
PUPPBBSHS	Agco, Challenger, MF Poly Pickup Band	35.74

JOHN DEERE

John Deere Round Baler

Models: 330, 335, 375, 385, 430, 435, 446, 447, 448, 456, 458, 458S, 466, 467, 468, 530, 535, 540, 545, 546, 547, 550, 556, 558, 566, 567, 568, 468S, 570, 572, 580, 582, 590, 592, 842, 852, 862, 458S, 468S
Replaces: CC32669, E85043, FH311772



Part No.	Description	Suggested List Price
PUPPBTOJD-G	JD Poly Pickup Band	44.32

John Deere Round Baler (Outer 3 on Mega Wide Head)

Models: Mega Wide Head
Replaces: FH311994, E96760



Part No.	Description	Suggested List Price
PUPPBEDJD	JD Poly Pickup Band	44.32

NEW HOLLAND

New Holland Square Baler with Roto Cutter Head

Models: 330, 340, 590, 590C, 595, BB940S, BB960S, BB940AS, BB940AP, BB960AS, BB9060S, BB9060P, BB9080S
Replaces: 84074345, 84214794, 84274385



Part No.	Description	Suggested List Price
PUPPBRCNH-Y	NH Poly Pickup Band	35.74

New Holland Big Square Baler

Models: 330, 340, 590, 590C, 595, BB940S, BB960S, BB940AS, BB940AP, BB960AS, BB9060S, BB9060P, BB9080S (No balers with rotary cutters)
Replaces: 84801630, 89837845, 85005357, 84214799, 84274388



Part No.	Description	Suggested List Price
PUPPBTONH-Y	NH Poly Pickup Band	44.32



Poly Pickup Bands (cont'd)

NEW HOLLAND



New Holland Round Baler

Models: BR7080, BR7090, BR770, BR770A, BR780, BR780A

Replaces: 87041203

Part No.	Description	Suggested List Price
PUPPBBRNH-Y	NH Poly Pickup Band	44.32

New Holland Round Baler with Extra Sweep Head (middle)

Models: BR740, BR740A, BR750, BR750A, BR780, BR780A, BR7060, BR7090

Replaces: 87055364

Part No.	Description	Suggested List Price
PUPPBRMNH-Y	NH Poly Pickup Band	44.32



New Holland Round Baler

Models: RB550, RB560

Replaces: 84310058

Part No.	Description	Suggested List Price
PUPPB54NH-Y	NH Poly Pickup Band	44.32



New Holland Round Baler with Extra Sweep Head (end)

Models: BR740, BR740A, BR750, BR750A, BR780, BR780A, BR7060, BR7090

Replaces: 86643380

Part No.	Description	Suggested List Price
PUPPBRONH-Y	NH Poly Pickup Band	44.32



New Holland Round Baler

Models: 644, 648, 654, 658, 664, 678, 688, BR730A, BR740, BR740A

Replaces: 86637149, 86512793

Part No.	Description	Suggested List Price
PUPPB6NNH-Y	NH Poly Pickup Band	44.32



NEW IDEA

New Idea Square Baler

Models: 7233, 7234, 733

Replaces: 700108607, 700129658

Part No.	Description	Suggested List Price
PUPPBTONH-S	CIH, Challenger, Hesston, New Idea Poly Pickup Band (Standard Bolts)	44.32



New Holland Round Baler

Models: 640, 644, 648, 650, 654, 658, BR7060, BR7070, BR740, BR740A, BR750, BR750A, RB450, RB460

Replaces: 86618414

Part No.	Description	Suggested List Price
PUPPB6WNH-Y	NH Poly Pickup Band	44.32



VERMEER

Vermeer Round Baler

Models: I, Super I, J, Super J, K, L, XL, Super M, N, Rancher, Rebel

Replaces: 89982001

Part No.	Description	Suggested List Price
PUPPB01VR	Vermeer Poly Pickup Band	44.32



July 2019